



350998

217/786-6892

4500 South Sixth Street  
Springfield, Illinois 62706

Refer to Macon County - 11580101 - Decatur/McKinney #2

November 14, 1979

Mr Paul McKinney  
Rural Route #8  
Box 48  
Decatur, Illinois 62522

Dear Mr McKinney

Your solid waste disposal facility located south of Decatur was inspected on October 25, 1976, by Gerald E Steele, representing this Agency.

The inspection disclosed the following condition(s) which constitute violations of the Environmental Protection Act and Chapter 7 of the Illinois Pollution Control Board Solid Waste Rules and Regulations

It was observed that pathological waste from a hospital, i e , I V and resperatory tubing, medical apparatus and empty containers was being accepted for disposal at your site If you desire to continue to accept said waste, or any other type of waste except those specified under Conditions in your permit, you must first obtain a Supplemental Special Waste Permit from this Division's Land Permit Section, which authorizes you to accept such waste

Daily cover is not being provided adequately on refuse in your current trench Materials deposited in the drainage ditch in the east central part of the site, and on the west slope of the southern hill were also seen needing more cover All solid waste received daily must be covered with a minimum of six (6) inches of compacted suitable natural earthen material by the end of that day's operation

The completed portions of your site have not received an adequate depth of final cover The areas found to be deficient the southern hill of the previously filled area

As the operation of this site has moved into Fill Area #2, the water monitor program outlined for this area in your permit must be complied with

Page 2

We suggest that you correct the aforementioned violations. A reinspection will be made in the near future to determine your progress.

Sincerely,

Monte M. Nienkerk, Central Region Manager  
Land Field Operations Section  
Division of Land/Noise Pollution Control

MMN GES jb/8854A/21-22

Enclosure Inspection Report

cc Division File ✓  
Central Region